

Avaya Exam 6002-1

6002.1 Avaya Aura(TM) Communication Manager and CM Messaging (R6.0) Implementation Exam

Version: 7.5

[Total Questions: 69]

Question No:1

When troubleshooting a system fault, if the web interface or SAT are unavailable, which method should be used?

- A. SAL
- B. TTY2
- C. CLI
- D. MODEM

Answer: C

Question No: 2

Which two series support RAID 5 configuration for CM6.0? (Choose two)

- A. S8730 Server with 8 GB RAM
- B. S8800 Server with 12 GB RAM
- C. S8510 Server with 8 GB RAM
- D. S8300D Server with 8 GB RAM

Answer: B,C

Question No: 3

Hunt group number 99, with group extension 4199, is administered for messaging.

Which command needs to be executed at the SAT terminal to troubleshoot hunt group 99?

- A. Shoe tracelog huntgroup 4199
- B. View logs real time huntgroup 99
- C. Display real time logs hunt group 99
- D. List trace hunt-group 4199

Answer: D

Question No: 4

A customer needs to set up SIP integration on Communication Manager Messaging Application 6.0

What are three pieces of information that are needed to meet this requirement? (Choose three)

- A. Signaling group number
- B. SIP domain
- C. Transport Method
- **D.** Extension length
- E. Hunt Group number

Answer: B,C,D

Question No:5

Which three are tests that can be performed to Verify a communication manager Messaging 6.0 application is working properly? (Choose three)

- **A.** Verify the hunt group status
- B. Check the messaging port status using the display port command
- C. Call the messaging Hunt Group
- **D.** Check the messaging port status using the status port command
- E. Perform message waiting indication test

Answer: A,C,E

Question No: 6

On a media gateway G450, which slots are permitted for the MM 342?

- **A.** V1 and V2
- **B.** V6 and V6
- **C.** V3 and V8



D. V5 and V7

Answer: C

Question No:7

A customer is planning to upgrade from CM 5X to CM 6.0 an existing 8510 server.

What is the total minimum memory requirement for this upgrade?

- A. 4 GB RAM
- B. 8 GB RAM
- **C.** 12 GB RAM
- **D.** 16 GB RAM

Answer: B

Question No:8

Which screen is used while upgrading the system platform from release 6.0.0.09 to release 6.0.0.11?

- A. Communication manager Web interface
- B. Console domain Server Management Path management
- C. Console domain Server Management Platform Upgrade
- D. Console domain Virtual Machine Management

Answer: C

Question No:9

Which three statements about CM_Duplex CM 6.0 are true?

A. Software duplication is available, but hardware duplication is not available.

Avaya 6002-1: Practice Test

- **B.** The S8510 server is not used for duplication
- C. Server duplication is configured via "Failover" option on CDROMs web interface
- **D.** S8730 with DAL 2 card does not support server duplication in CM 6.0.
- E. The CM duplex template supports CMM

Answer: A,B,D

Question No: 10

Which gateway command resets the Gateway back to factory default?

- A. Reset
- **B.** Restart
- C. Softboot
- **D.** Nvram init

Answer: D

Question No: 11

A technician wants to test and see if the voice channel between two IP phones

Which command in site administration terminal (SAT) can be used to determine?

- A. Status station <extension>
- **B.** Status shuffling <extension>
- C. List station <extension>
- D. Test station <extension>

Answer: A

Question No: 12

Which Ethernet port on S8800 server is for server duplication?