

Cisco 640-792

TPTECH

Version: 4.1

QUESTION NO: 1

Which port is indicated on the right Secondary Codec for the CTS-3210?

- A. Right Display
- B. Right Camera
- C. Center Display
- D. Left Display

Answer: B

Explanation:

QUESTION NO: 2

Which port do you connect to on the Primary Codec in order to establish an Ethernet connection between your laptop and the Cisco TelePresence 3000 equipment?

- A. Video port
- B. Network port
- C. IP Phone port
- D. Secondary Camera port

Answer: B

Explanation:

QUESTION NO: 3

Which size and type of tool is required to loosen the screws that allow rotational adjustment of the CTS-3010 cameras?

- A. #1 Phillips screwdriver
- B. 5.0 mm Allen wrench
- C. #3 Phillips screwdriver
- D. 3.0 mm Allen wrench

Answer: D

Explanation:

QUESTION NO: 4

Which four functions does Cisco TelePresence rely on Cisco Unified Communications Manager for? (Choose four)

- A. Configurations
- B. Software upgrades
- C. Management
- D. Call processing
- E. Scheduling meetings
- F. Microphone calibration

Answer: A,B,C,D

Explanation:

QUESTION NO: 5

Which three of the following components are included on the Cisco TelePresence 3210? (Choose three.)

- A. One boardroom-style table with a second row
- B. One boardroom-style table
- C. One 40" external display
- D. Nine table microphones
- E. Four LED light fixtures


Answer: A,C,D

Explanation:

QUESTION NO: 6 DRAG DROP

Click and drag the OSI reference layer on the left to the corresponding Internet protocol suite on the right.

Layer 2 - Data Link	IP
Layer 3 - Network	Email
Layer 4 - Transport	TCP
Layer 7 - Application	ARP

Answer:**Explanation:**

Layer 2 Datalink – ARP

Layer 3 – Network – IP

Layer4 – Transport – TCP

Layer7 – Application - Email

QUESTION NO: 7

Which three of the following are benefits of Cisco TelePresence Manager? (Choose three)

- A. Bulk software upgrades of endpoints
- B. Calendaring integration and management
- C. One-Button-to-Push meeting access
- D. Allow for content sharing
- E. Concierge services

Answer: B,C,E

Explanation:

QUESTION NO: 8

Which two hardware components are optional for the Cisco TelePresence 1000? (Choose two)

- A. One Cisco Unified IP Phone 7975G
- B. One external display
- C. One high-definition camera
- D. One Auxiliary Control Unit

Answer: B,D

Explanation:

QUESTION NO: 9



Which port is indicated on the Auxiliary Control Unit for the CTS-1100 and 1300?

- A. Auxiliary Collaboration Display
- B. Serial Control for Projector
- C. Lights
- D. Serial Control for Dimmer Box

Answer: B

Explanation:

QUESTION NO: 10 DRAG DROP